



CHIP RESETTER FOR CANON PGI-220 Black /CLI-221 Black, CLI-221 Cyan, CLI-221 Magenta, CLI-221 Yellow

The OEM **CANON** PGI-220 Black / CLI-221 Black/ CLI-221 Cyan/ CLI-221 Magenta/ CLI-221 Yellow have chips, which serve to monitor the ink levels and to provide an on-screen message of “empty” when the ink levels run out. Our **CHIP RESETTER** allows you to restore the ink level monitoring function, and thereby override the “empty” or “out of ink” messages after you have refilled and reset your cartridge. This resetter is designed and guaranteed to reset the ORIGINAL Canon chips, but may not work on compatible (generic brand) chips. This **CHIP RESETTER** is versatile: It will automatically identify the cartridge model and detect whether the chip on the cartridge is in a good state or not, then reset the chip. Since it is operated by a small replaceable battery, the number of resets it can offer is unlimited.

The following OEM (original brand Canon) cartridge chips can be reset: CANON PGI-220 Black /CLI-221 Black, CLI-221 Cyan, CLI-221 Magenta, CLI-221 Yellow

Corresponding printer models:

This resetter works with all Canon cartridges that are used in printers such as the Canon PIXMA iP3600, iP4600, iP4700, MP560, MP620, MP640, MP980, MP990, MX860, MX870, PMFP1, PMFP3, SFP1, SFP2, MP610, MX860 and others utilizing CLI221 / PGI220 ink cartridges with chips.